



FEDERAL AVIATION ADMINISTRATION



**FLIGHT ADVISORY
GPS INTERFERENCE TESTING**

FORT BLISS TEXAS (BLISS) 19-02

**08 – 13 June 2019
Fort Bliss, TX**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

A. Location: Centered at 321025N1061523W or the ELP VOR 355 degree radial at 22NM.

B. Dates and times (**Dates and times are based on GMT (Z).**):


8 JUN 19	1001Z – 2359Z	
9 – 12 JUN 19	0001Z – 0159Z	1001Z – 2359Z
13 JUN 19	0001Z – 0159Z	1001Z – 1459Z

C. Duration: Each event may last the entire requested period.

D. NOTAM INFO: NAV GPS (BLISS GPS 19-02) (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 134NM RADIUS CENTERED AT 321025N1061523W (ELP355022) FL400-UNL, 128NM RADIUS AT FL250, 127NM RADIUS AT 10000FT, 128NM RADIUS AT 4000FT AGL, 106NM RADIUS AT 50FT AGL.

E. Pilots are encouraged to report anomalies in accordance with the Aeronautical Information Manual (AIM) paragraphs 1-1-13 and 5-3-3.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.



BLISS 19-02 GPS INTERFERENCE TESTING